Department of Industrial Relations Division of Occupational Safety and Health ELEVATOR UNIT HQS 6980 Santa Teresa Boulevard, Suite 130 San Jose, CA 95119 Phone: 408.362.2120 Fax: 408.362.2131



**October 6, 2010** 

**CIRCULAR LETTER E-10-04** 

TO: Installers, Manufacturers of Conveyances and Related Equipment and, Other Interested Parties

**SUBJECT: Coated Steel Belt Monitoring** 

The Elevator Safety Orders require routine inspection of the suspension means of an elevator to assure its safe operation.

The California Labor Code Section 7318 allows the Division to promulgate special safety orders in the absence of regulation.

As it is not possible to see the steel cable suspension means of a Coated Steel Belt, a monitoring device which has been accepted by the Division is required on all Coated Steel Belts which will automatically stop the car if the residual strength of any belt drops below 60%. The Device shall prevent the elevator from restarting after a normal stop at a landing.

The monitoring device must be properly installed and functional. A functioning device may be removed only after a determination has been made that the residual strength of each belt exceeds 60%. These findings and the date of removal are to be conspicuously documented in the elevator machine room. The removed device must be replaced or returned to proper service within 30 days.

If upon routine inspection, the monitoring device is found to be in a non-functional state, the date and findings are to be conspicuously documented in the elevator machine room.

If upon inspection by the Division, the monitoring device is found to be nonfunctional or removed, and the required documentation is not in place, the elevator will be removed from service.

If the device is removed to facilitate belt replacement, it must be properly installed and functional before the elevator is returned to service.

A successful test of the device's functionality shall be conducted once a year.

This circular does not preempt the Division from adopting regulations in the future which may address the monitoring of Coated Steel Belts or any other suspension means.

Page 2

This circular does not create an obligation on the part of the Division to permit new conveyances utilizing Coated Steel Belts.

Debra Tudor Principal Engineer DOSH-Elevator Unit HQS